ABSTRACT

The machine tool transmission, in particular a spindle transmission, in which the force and torque transfer takes place directly from the pinion shaft (3) of the transmission (1) to the spindle, where the spindle is conveniently arranged in a coaxial configuration with the pinion shaft (3).

4/20/06 -11:09 AM